

Oil Field Environmental Incident Summary

Incident: 20151221124152 **Date/Time of Notice:** 12/21/2015 12:41

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: JDT 24-10NH

Field Name: CEDAR HILLS

Well File #: 17482

Date Incident: 12/20/2015 **Time Incident:** 14:00

Facility ID Number:

County: BOWMAN

Twp: 130

Rng: 106

Sec: 10

Qtr:

Location Description:

Submitted By: Justin Collins

Received By:

Contact Person: Justin Collins
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels	4	barrels
Brine	4	Barrels	4	Barrels	4	barrels

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 12/28/2016 **Clean Up Concluded:** 1/15/2016

Risk Evaluation:

None

Areal Extent:

20 yards x 40 yards

Potential Environmental Impacts:

Pasture top soil

Action Taken or Planned:

Shut in flow line. Built berm around spill until vac truck arrived. Sucked up standing fluid, removed contaminated material.

Wastes Disposal Location: Little Missouri Special

Agencies Involved:

Updates

Date: 12/21/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release did not stay on location. Further followup necessary.

Date: 1/5/2016 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site 11:35 a.m. The weather was sunny, 14°F, with wind calm. I talked to a company rep; he took me to the spot of the pipeline break. The pipeline broke just on the west side of the well JDT 1-10F, which is located about a quarter mile southwest of the well indicated on the incident report. The company rep indicated that a lot of soil had been removed. There was no piled soil at the break area, and the area has been leveled off. More followup needed next growing season.
46.09088, - 103.92880